



CANAL DE PANAMÁ

September 17, 2018

WAYPOINT PANAMA
Edif. High Tech Plaza
Bella Vista, Republic of Panama
Fax 264-6532

Gentlemen:

REFERENCE: M/V CS CAPRICE (SIN 6008245)

On September 14, 2018, when the above referenced vessel was presented for transit of the Panama Canal the Master informed that the vessel's main engine controls did not function from the bridge and the engine control room; the engine is controlled from the emergency control station. A Transiting Vessel Inspector embarked and the Chief Engineer informed that the problem was located in the main engine governor controls, which was solved. Several components were adjusted and replaced. The Inspector tested the engine controls, from all control stations, and the engine was submitted to a twelve starts test to satisfaction.

Vessels transits are a joint effort. The cooperation of all concerned parties is necessary to assure safe and efficient transits.

Please inform the Principals of this and express my appreciation to the Master, the Chief Engineer and the crew for their cooperation.

Sincerely,

Guillermo Manfredo Jr.
Canal Operations Captain
Executive Manager for Transit Operations

VET/caf